Volkswagen汽車機油更換服務

引擎
- 更換機油及機油過濾器
- 檢查冷卻液水平
- 原廠電腦VAS診斷儀作引擎管理系統檢查

制動系統
- 檢查制動液狀況/量
- 檢查制動皮剩餘厚度
- VAS電腦診斷ABS/ESP安全系統及電子手制系統(如適用)

轉向系統
- 檢查轉向系統油量(如適用)

電器系統
- 檢查玻璃洗滌水量
- 重設下次回廠檢查日期提示

其他
- 檢查所有門、頭尾冚較位，如有需要加添潤滑劑

Volkswagen Oil Change Service

Engine
- Change engine oil and oil filter
- Check engine coolant level
- Engine management system diagnosis using VAS diagnostic tester

Brake System
- Check brake fluid condition/level
- Front and rear brake pads/linings: Check thickness
- ABS/ESP, electronic parking brake system: Diagnosis using VAS tester (if applicable)

Steering System
- Check steering oil level (if applicable)

Electrical System
- Windscreen wash/wipe system: Check fluid level
- Reset service interval display

Miscellaneous
- Check door arrester, hinges (door, hood, truck), grease if necessary

Volkswagen汽車機油更換及一般性檢查包括之物料及零件：高級全合成機油(VW504 00/507 00)及機油隔
Parts and materials included in Volkswagen Oil Change & General Inspection: Synthetic engine oil (VW504 00/507 00) & oil filter

Volkswagen汽車機油更換服務價目表
Volkswagen Oil Change Service Price List

型號 Model	價錢 Price (HK$)
Polo	$1,480
Jetta 1.4	$1,620
Jetta 2.0/2.0T	$1,810
Golf / Scirocco 1.4	$1,620
Golf 1.6/2.0/2.0T/R/ Scirocco 2.0T	$1,810
Passat (CC) 1.8/1.8T/2.0/2.0T	$1,830
Golf R32/Passat 3.2 Passat CC 3.6/Passat R36	$1,900
Tiguan	$1,830
Touran	$1,750
Eos	$1,790
New Beetle	$1,710
Touareg 3.2	$2,560
Touareg 3.6/4.2	$3,070
Phaeton 3.2	$2,560
Phaeton 3.6/4.2	$2,800
Caravelle (T5)	$2,520
Sharan	$1,900

以上收費如有更改，恕不另行通知。
Prices are subject to change without prior notice.